HIKVISION
First Choice for Security Professionals

Network Video Recorder

Version: V4.40.016 build 200803

Release Note

(2020-8-3)

Firmware Basic Information	Firmware Version:	V4.40.016 build200803
	SDK Version:	V6.1.4.40_build20200428
	Play Library:	V7.3.8.45
	Web component:	V4.0.1 build200611
	OpenSDK Version:	V2.4.0

Reason of Upgrade

Fix some issues and optimize product performance.

Fixed issues

1.Fix the problem of insufficient NVR power supply caused by high-power camera access.

2. Fix the problem that the NVR motherboard has a small probability that some slots cannot recognize the hard disk.

3. Fixed the problem that the HCP platform could not receive People Counting IP camera alarms.

Related product list:

I series NVR	DS-9600NI-I16, DS-9600NI-I8
	DS-8600NI-I8, DS-7700NI-I4(B)(/P)
	DS-7600NI-I2(/P)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.

- Hikvision doesn't give any guarantee for old models' stock.

- Hikvision is not liable for any typing or printing errors.

- For special model's change details, please contact our local technical support team.