

Network Camera Firmware Version: V5.8.0 SP3

Release Note

Firmware Basic Information	Firmware Version: V5.8.0 build 230706
---------------------------------------	---------------------------------------

1. New Features

NA

2. Modify Features

- Fixed the problem of people counting data auto-replenish to 0 when network recovers.
- Support pass by data auto-replenish when network recovers.
- Fixed the problem that after device restart, OSD count data delay.
- Fixed OSD jump issue when deployment time starts.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Supported Product List	
Product Category	Model Number
7 Series DeepinView Camera	iDS-2CD7146G0/C-IZS

Note: Models in red font are newly released models.