

Network Camera Firmware Version: V5.5.120-SP

Release Note(Internal)

(2021-04-20)

Firmware	Firmware Version 1:	V5.5.120 build210224
Basic Information	Firmware Version 2:	V5.5.120 build210318

1. New Features

Firmware version 1:

1. Newly added 4MP models of overseas 1 series and HILOOK series: DS-2CD1043G0-IUF(C), DS-

2CD1143G0-IUF(C), DS-2CD1343G0-IUF(C), DS-2CD1043G0-I(C), DS-2CD1143G0-I (C), DS-

<u>2CD1343G0-I (C), IPC-B140H (C), IPC-D140H (C), IPC-T140H (C). Support true WDR, support English</u> and Ukrainian;

2. Newly added overseas 2MP 2 series cameras, the product models are DS-2CD2021G1-I(C), DS-

2CD2121G0-I(C), DS-2CD2121G0-IS(C), DS-2CD2321G0-I/NF(C). Support true WDR, support intrusion

detection and line crossing, support 32 languages.

Firmware Version 2:

<u>1. Newly added overseas 1 series and 2MP models of HILOOK series: DS-2CD1023G0-I(C), DS-2CD1021-I(F), DS-2CD1123G0-I(C), DS-2CD1121-I(F), DS-2CD1323G0-I(C), DS-2CD1323G0-I(F), DS-2CD1023G0-IUF(C), DS-2CD1123G0-IUF(C), DS-2CD1323G0-IUF(C), IPC-B121H(C)), IPC-T221H(C), IPC-D121H(C)</u>

2. Improved Features

<u>None</u>

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

<u>Remarks:</u>

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.



- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998