

## IPCG\_OP\_G5\_V5.8.20 Release Note (2023-05-08)

<b>Firmware Basic Information</b>	Firmware Version: V5.8.20 build 230426
---	--

### Features

- **New function**

1. Fix invalid sound size adjustment issue

### Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

#### **Remarks:**

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)

<b>Supported models</b>	
<b>Product series</b>	<b>Product models</b>
IPC 6 Series	DS-2CD6425G2-C1(O-STD)
IPC 6 Series	DS-2CD6445G2-C1/HDMI(O-STD)
IPC 6 Series	DS-2CD6425G2-C2(O-STD)