

## Network Camera Firmware Version: V5.7.0 Release Note

| Firmware    |                   |                    |
|-------------|-------------------|--------------------|
| Basic       | Firmware Version: | V5.7.0 build211009 |
| Information |                   |                    |

## **Features**

- 1. Improved Features
  - Fix security issue in ISAPI.

## **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after

the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this

action.

For any questions and request for this firmware, please contact our local technical support team.

## <u>Remarks:</u>

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.



• Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: overseabusiness@hikvision.com

| Supported Product List |                             |  |
|------------------------|-----------------------------|--|
| Product Category       | Model Number                |  |
| 2 Series Solar         | DS-2XS2T41G0-ID/4G/C04S05   |  |
| 2 Series Solar         | DS-2XS2T47G0-LDWH/4G/C18S40 |  |
| 2 Series Solar         | DS-2XS2T47G0-LDW/4G/C18S40  |  |
| 6 Series Solar         | DS-2XS6A87G1-L/C36S80       |  |