

IPCG_DC_G5_V5.8.0 Release Note (2023-05-11)

Firmware Basic Information	Firmware Version: V5.8.0 build 230508
---	---------------------------------------

Features

- **New function**

1. Fix the issue of OSD not counting within 10 seconds after restarting

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com

Supported models	
Product series	Product models
IPC 6 Series	DS-2CD6825G0/C-I(2mm)(B)(O-STD)
IPC 6 Series	DS-2CD6825G0/C-IVS(2mm)(B)(O-STD)
IPC 6 Series	DS-2CD6825G0/C-IS(2mm)(B)(O-STD)
IPC 6 Series	DS-2CD6825G0/C-IV(2mm)(B)(O-STD)
IPC 6 Series	DS-2CD6825G0/C-IV(2mm)(B)(O-NEU)
IPC 6 Series	DS-2CD6825G0/C-IVS(2mm)(B)(O-NEU)
IPC 6 Series	DS-2CD6825G0/C-I(2mm)(B)(O-NEU)
IPC 6 Series	DS-2CD6825G0/C-IS(2mm)(B)(O-NEU)