

Network Camera-V5.7.2_SP1 Release Note-H8 (2022-06-20)

Firmware Basic Information Firmware version: V5.7.2 build220620

New Features

Modify Function

Fix Metadata memory leak in face capture mode, update DSP and APP to fix this issue.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,

China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com



Supported Product List	
Product Category	Model Number
2 series	DS-2CD2087G2-LUK(2.8mm)(D)(O-STD)(Prototype)
2 series	DS-2CD2087G2-LUK(4mm)(D)(O-STD)(Prototype)
2 series	DS-2CD2087G2-LUK(6mm)(D)(O-STD)(Prototype)
2 series	DS-2CD2087G2-LUK(2.8mm)(D)(O-NEU)(Prototype)
2 series	DS-2CD2087G2-LUK(4mm)(D)(O-NEU)(Prototype)
2 series	DS-2CD2087G2-LUK(6mm)(D)(O-NEU)(Prototype)