

IPC_G5_V5.7.0 Release Note (2022-12-27)

Firmware Basic Information	Firmware Version: V5.7.0 build221128
---	--------------------------------------

Features

● New function

1. Fix the problem of slow 4G startup during non live time
2. Optimize the quick start time
3. The picture at 10-11s of small video is split and the probability of not capturing
4. Night image quality optimization
5. PIR performance supplementary test and improvement after equipment+filter
6. After the improvement of infrared non confocal, the image effect is optimized and traced
8. Optimizes the probability of not snapping

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from

published specifications. Current characterized errata are available on request.

- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com

Supported models	
Product series	Product models
IPC 6 Series	DS-2XS6F45G0-IC0/4G(2.8mm)(O-STD),
IPC 6 Series	DS-2XS6F45G0-IC0(2.8mm)(O-STD),
IPC 6 Series	DS-2XS6F45G0-IC1/4G(2.8mm)(O-STD)/EU,
IPC 6 Series	DS-2XS6F45G0-IC2/4G(2.8mm)(O-STD)/EU,
IPC 6 Series	DS-2XS6F45G0-IC1(2.8mm)(O-STD)/EU,
IPC 6 Series	DS-2XS6F45G0-I9C1/4G(2.8mm)(O-STD)/EU