

IPC_G5_V5.8.10 SP Release Note (2023-04-07)

Firmware		
Basic	Firmware Version:	V5.8.10 build230407
Information		

Features

New function

Support the latest ONIVF certification

Improved Features

- 1. Fixed the issue of 485.
- 2. Fixed the camera picture blur problem caused by MCU.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com



Supported models		
Product series	Product models	
IPC 6 Series	DS-2CD6D22G0-IS(2.8mm)(O-STD)	
IPC 6 Series	DS-2CD6D42G0-IS(2.8mm)(O-STD)	
IPC 6 Series	DS-2CD6D22G0-IS(4mm)(O-STD)	
IPC 6 Series	DS-2CD6D42G0-IS(4mm)(O-STD)	
IPC 6 Series	DS-2CD6D22G0-IS(6mm)(O-STD)	
IPC 6 Series	DS-2CD6D42G0-IS(6mm)(O-STD)	
IPC 6 Series	DS-2CD6D22G0-IS(2.8mm)(O-NEU)	
IPC 6 Series	DS-2CD6D42G0-IS(2.8mm)(O-NEU)	
IPC 6 Series	DS-2CD6D22G0-IS(4mm)(O-NEU)	
IPC 6 Series	DS-2CD6D42G0-IS(4mm)(O-NEU)	
IPC 6 Series	DS-2CD6D22G0-IS(6mm)(O-NEU)	
IPC 6 Series	DS-2CD6D42G0-IS(6mm)(O-NEU)	
IPC 6 Series	DS-2CD6D42G0-IS(2.8mm)(O-NEU)(O1)	