

# IPCP\_H10\_V5.7.0 Release Note

## (2023-3-28)

<b>Firmware Basic Information</b>	Firmware Version: V5.7.0 Build230221
---	--------------------------------------

### Modified Features

- supported the ONVIF report
- Optimized the functions of the previous version

### Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

#### **Remarks:**

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)

## Supported Product List

<b>Firmware</b>	<b>Model</b>
IPCP_H10_EN_STD/NEU_5.7.0_230221.zip	DS-2CD6924G0-IHS(2.8mm)(D)
	DS-2CD6944G0-IHS(2.8mm)(D)
	DS-2CD6984G0-IHS(2.8mm)(D)